

PRODUCT BULLETIN

10081828 TruTurn® Brake Drum Update / 10001783 CastLite® Obsolescence

ConMet is updating the wheel stud hole diameter in the 10081828 TruTurn brake drum from 1.1" to 1.35" to allow it to be used in both hub-piloted and stud-piloted (also called ball seat nut or "Budd") applications. The drum pilot, fit and performance of the 10081828 will remain the same. This is a running change, the updated drum will begin shipping after approximately May 21st.

Additionally, with the updates to the 10081828, we are simplifying our product offering and obsoleting the 10001783 CastLite drum. The 10081828 can be used in all applications where the 10001783 was used previously. The 10001783 will be available while supplies last.



10001783 15x4" CastLite



10081828 15x4" TruTurn

Please contact your ConMet representative with any questions regarding this change.

The information in this Product Bulletin is intended as a reference source only. Consolidated Metco does not assume any liability in the event of improper use or mis-match of components. For additional information, visit our web site at conmet.com or call 800.547.9473.