


# WHEEL SEAL

## Leakage Identification

**NOTE:** Always follow your company's safety procedures.

Hubs Equipped with **Drum Brakes**:



Seal shows no signs of reoccurring moisture or seepage onto the seal face, ABS ring, hub, or brakes.



### X

### Leaking Seal

Seal is actively leaking, wetting the tire, wheel, hub, ABS ring, or brakes with oil. **NOTE:** A seal in any of these conditions meets out-of-service criteria and should be replaced.



For additional information on seal care, including more detailed instructions, go to conmet.com/seals




# WHEEL SEAL

## Leakage Identification

 $\textbf{NOTE:} \ Always follow your company's safety procedures.$ 

Hubs Equipped with Air Disc Brakes:



No signs of oil leaking or running down the tire, wheel, rotor, brake pads, or caliper.



#### **X** Leal

#### **Leaking Seal**

Seal is actively leaking, wetting the tire, wheel, hub, rotor, ABS ring, brake pads, or caliper with oil. **NOTE:** A seal in any of these conditions meets out-of-service criteria and should be replaced.



ConMet | 5701 SE Columbia Way, Vancouver, WA 98661 | 800.547.9473 | conmet.com

